# SOUTHERN® PRIDE BBQ SMOKERS

## **SERVICE BULLETIN**

SP2016-001 Revision 2 September 18, 2024

Before performing any service always follow applicable safety precautions.

### **Product Door Gasket Lengths**

**Affected Products:** Current models (as of revision date)

Affected Serial Range: N/A
Related Issue #: N/A

**Revision 1:** Removed SC-200, DH-65 and SPK-1000

Added SC-300

Changed SP-700 length

**Revision 2:** Added SC-100

#### **Issue Description:**

The appropriate product door gasket lengths for cutting bulk gasket (part number 070002) to size.

#### **Actions Required:**

|             |               | Product Door   | Z bracket        |
|-------------|---------------|----------------|------------------|
| Part Number | Model         | Opening Length | (on door) length |
| 070103      | SC-100        | 99-1/4"        | N/A              |
|             | "C" in s/n    | 2521mm         |                  |
| 070102      | SC-300        | 120"           | N/A              |
|             |               | 3048mm         |                  |
| 070092      | SRG-400       | 138"           | N/A              |
|             |               | 3505mm         |                  |
| 070088      | MLR-150       | 81-1/2"        | N/A              |
|             |               | 2070mm         |                  |
| 070080      | SPX-300       | 107"           | 21"              |
|             |               | 2718mm         | 533mm            |
| 070081      | SPK-500       | 134-1/2"       | 21"              |
|             | "K" in s/n    | 3416mm         | 533mm            |
| 070089      | SP-700        | 152"           | 27"              |
|             |               | 3861mm         | 686mm            |
| 070090      | MLR-850       | 100"           | N/A              |
|             |               | 2540mm         |                  |
| 070101      | SPK-1400      | 139-1/2"       | 27"              |
|             | "K14A" in s/n | 3543mm         | 686mm            |
|             | •             |                |                  |

#### **Additional Comments:**

The customer may need to trim the gasket to achieve their desired fit.

#### **Secondary Distribution:**

Service technicians within the Distributor's organization.

Service companies.

#### **For Additional Information:**

Southern Pride Technical Service: (800) 437-2679