

Products: 120v Gas Rotisserie Smokers

Serial Range: Starting with: R1500281

X3001089

K5001860

P70A0386

R8500094

K14A0125

Release Date: July 6, 2020

Relays for the Proximity Sensor/Interlock Switch and Smoke Extractor/VSP Hood System

Relay 444011 has been discontinued by the manufacturer. It will be replaced by relay 444023 and socket 444024. The new relay and socket provide numerous benefits over the old relay:

- All wiring goes into the socket allowing the relay to be changed without handling the wires.
- The top of the relay has an LED indicator and mechanical flag that shows when there is power to the coil of the relay.
- The top of the relay has a locking test button to hold the contacts in the closed position and can be used as a manual switch in place of the coil.



444011

Additional Comments:

A limited number of 444011 will be available as replacement parts. When those are depleted, there will be a kit to replace relays 444011 with relay and socket 444023 and 444024. Refer to Service Bulletin SP2020-001 for more details.



444023

Refer to the latest version of the Owner's Manual for changes to the wiring for the relays.

Secondary Distribution:

Service technicians within the Distributor's organization.
Service companies.

For Additional Information:

Southern Pride Technical Support: (800) 437-2679



444024